



P1002-1	AC 3.8V	1
P1002-2	AC 3.8V	2
P1002-3	REG -30V	3

P6505	REG +15V	P1011-3
	AC 3.8V	P1011-2
	AC 3.8V	P1011-1

P6504	LEVEL M 1	P4310-1
	LEVEL M 2	P4310-2
	TRACKING	P4310-3

P6503	GND	P4311-1
	REC MUT	P4311-2
	TRACK	P4311-3

NOTE: THE MEASUREMENT MODE OF THE DC VOLTAGE ON THIS DIAGRAM IS STOP MODE.